



Notes / screenshots for MSC end supports


2012-08-02

Silber





Aluminum "PP Bridge" parts do NOT get glued to the carbon fiber plates. These get bolted-on during assembly at Brookhaven.



Backing ring gets glued
to ESC stiffener plate.
Use 4x 5mm pin holes in
each to align.

Plate

Backing ring

(counterbores of
the backing ring
should be on
outside, obviously)

